


ILS RWY 3R (CAT II & III)
DETROIT METRO WAYNE COUNTY (DTW)

MISSED APPROACH: Climb to 1100 then climbing right turn to 4000 on DXO VOR/DME R-122 to GAAGE/DXO 16.1 DME and hold.

ALSF-2

ELEV 645	D	TDZE 633
HIRL all runways REIL Rwy 3L, 9L, 9R and 21R TDZ/CL Rwy 3R, 4L, 4R and 22R		



CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED