

ILS or LOC RWY 7R
CHORAGE INTL (ANC) (PANC)

MISSED APPROACH: Climb to 780 then climbing right turn to 3000 on heading 230° and on TED VOR/DME R-210 to JUKEP/TED 15 DME and hold. (TACAN aircraft climb to 780 then climbing right turn to 3000 on heading 230° and EDF TACAN R-210 to JUKEP/EDF 22.6 DME and hold).

ANCHORAGE
113.15 TED
Chan 78(Y)

ELMENDORF
Chan 81
EDF
(113.4)

LOCALIZER
111.3
I-ANC
Chan 50

TACAN MISSED APCH FIX

JUKEP
TED [15]
EDF [22.6]

Procedure NA for arrival on ENA VOR/DME airway radials 028 CW 048.

ALTERNATE MISSED APCH FIX

ELIJAH
117.6 ENA
Chan 123

JUKEP
ENA [34.2]

WEWWO
I-ANC [12.4]
3300
1600

TULLI
I-ANC [6.7]

WVDA
I-ANC [4.8]

ELIAS INT
I-ANC [18.6]
ENA [37.4]

MSA TED 25 NM
5600
1800
8900

ELEV 151
D
TDZE 7R 132
TDZE 7L 128

REIL Rwy 33
 TDZ/CL Rwsy 7L and 7R
 HIRL all Rwsy