## DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 18: Climb on heading 192° to 2500 before proceeding on course or as assigned by ATC, thence . . . .

TAKEOFF RUNWAY 36: Climb on heading 357° to 1400 before turning southbound or as assigned by ATC, thence . . .

.... expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR2.EAKER) MC ALESTER TRANSITION (NANDR2.MLC) OKMULGEE TRANSITION (NANDR2.OKM) ROLLS TRANSITION (NANDR2.ROLLS) TULSA TRANSITION (NANDR2.TUL) WILL ROGERS TRANSITION (NANDR2.IRW) ZEMMA TRANSITION (NANDR2.ZEMMA)

V